



Bulletin Number: 88-6-18A  
Reference Number: 836105R  
Publish Date: 2/88

PONTIAC DIVISION

'88



Dealer  
Service  
Bulletin



**Subject:** CAMSHAFT LOBE LIFT

## Models

**Affected:** 1985 THROUGH 1988 2.5L ENGINE  
SPECIFICATIONS FOR 6000, GRAND AM AND  
FIERO MODELS

*This bulletin is being revised to correct the metric conversion for the camshaft lobe lift.*

### SERVICE MANUAL UPDATE

In the engine specifications charts near the end of the 2.5L engine section, change Camshaft Lobe Lift to:

.232 inches, 5.8928 mm

SERVICE DEPARTMENT  
PONTIAC DIVISION  
GENERAL MOTORS CORPORATION

Pontiac bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer." They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your Pontiac dealer for information on whether your vehicle may benefit from the information.

Read, Initial & Pass On

• Service Supervision

• Parts

• Accounting